

Title (en)

Method for repairing a coating surface.

Title (de)

Verfahren zur Wiederherstellung einer Oberflächenbeschichtung.

Title (fr)

Méthode pour réparer une surface de revêtement.

Publication

EP 0348917 B1 19940316 (EN)

Application

EP 89111711 A 19890627

Priority

JP 15684388 A 19880627

Abstract (en)

[origin: EP0348917A2] A method for repairing the surface of a coating involves the step of acting a compound with a Vickers hardness above Hv 2,000 g/mm<2> on the surface thereof by pressing the compound with a buff at a uniform surface pressure ranging from 2 to 20 g/cm<2>. This method permits repairing a coating surface with a scrape or scratch to a coating surface of high quality without causing any fade on the surface thereof.

IPC 1-7

C09K 3/14

IPC 8 full level

B05D 3/12 (2006.01); **B24B 37/00** (2012.01); **B24B 37/005** (2012.01); **C09K 3/14** (2006.01)

CPC (source: EP KR)

B24B 37/00 (2013.01 - KR); **C09K 3/14** (2013.01 - EP)

Cited by

GB2329133A

Designated contracting state (EPC)

DE FR GB

DOCDB simple family (publication)

EP 0348917 A2 19900103; **EP 0348917 A3 19910227**; **EP 0348917 B1 19940316**; DE 68913826 D1 19940421; DE 68913826 T2 19940630; JP H026880 A 19900111; JP H0615063 B2 19940302; KR 900000130 A 19900130; KR 940009091 B1 19940929

DOCDB simple family (application)

EP 89111711 A 19890627; DE 68913826 T 19890627; JP 15684388 A 19880627; KR 890008977 A 19890627