

Title (en)

Rotor repair method and rotor repair apparatus

Title (de)

Verfahren und vorrichtung zur reparatur eines rotors

Title (fr)

Procédé et dispositif pour réparer un rotor

Publication

**EP 2256226 A1 20101201 (EN)**

Application

**EP 10174475 A 20040823**

Priority

- EP 04772022 A 20040823
- EP 10174475 A 20040823

Abstract (en)

A to-be-repaired damaged part, which occurs in a rotor (1), is removed and shaped by machining or grinding (S1). The shaped surface, from which the to-be-repaired damaged part is removed in the step (S1), is roughened by a blasting process (S2). A coating is formed on the surface, which is roughened in the step (S2), by a high-velocity flame spray apparatus (S3). The coating, which is formed in the step (S3), is finished by machining or polishing (S4). A defect inspection is performed to check presence/absence of a defect (S5). A dimensional/quality inspection is performed for the part repaired (S6) in the step (S5).

IPC 8 full level

**C23C 4/00** (2006.01); **B05B 13/02** (2006.01); **B23K 9/00** (2006.01); **B23K 9/04** (2006.01); **C23C 4/12** (2006.01)

CPC (source: EP)

**B05B 13/0442** (2013.01); **C23C 4/02** (2013.01); **C23C 4/08** (2013.01); **C23C 4/129** (2016.01); **C23C 4/18** (2013.01); **B05B 7/205** (2013.01)

Citation (applicant)

- JP H04232244 A 19920820 - MAZDA MOTOR
- JP H0920975 A 19970121 - NIPPON STEEL CORP, et al

Citation (search report)

- [XY] WO 9942632 A1 19990826 - MONITOR COATINGS & ENG [GB], et al
- [Y] WO 9605331 A1 19960222 - TELATEK OY [FI]
- [T] JP 2000282210 A 20001010 - NAT RES INST METALS

Designated contracting state (EPC)

DE FR GB

DOCDB simple family (publication)

**EP 2256226 A1 20101201**

DOCDB simple family (application)

**EP 10174475 A 20040823**