

Title (en)

Method for breaking a roving in preparation for automatic removal of bobbins from spindle banks and pressing finger for carrying out this method

Title (de)

Verfahren zum unterbrechen der Faserlunte als Voraussetzung für das automatische abheben der Spulen auf Spindelbänken und Pressfinger zur Durchführung dieses Verfahrens

Title (fr)

Procédé de casse de la mèche en vue de la levée automatique des bobines sur des bancs à broches et doigt presseur mis en oeuvre par ce procédé

Publication

EP 0692561 B1 20000503 (FR)

Application

EP 95440038 A 19950704

Priority

FR 9408883 A 19940713

Abstract (en)

[origin: EP0692561A1] To sever the slubbing at a bobbin for automatic bobbin (1) doffing at the spindle rail, to allow the operative to grip the slubbing end and secure it, the slubbing is brought down to the bottom of the bobbin (1) at the end of winding. The slubbing is wound several times round the bobbin base and then brought upwards into a restricted over-winding. It is then brought down to sever the slubbing at the upper part of the bobbin. <IMAGE>

IPC 1-7

D01H 9/16; D01H 1/38

IPC 8 full level

D01H 7/32 (2006.01); **D01H 9/16** (2006.01)

CPC (source: EP US)

D01H 9/16 (2013.01 - EP US)

Designated contracting state (EPC)

DE ES IT

DOCDB simple family (publication)

EP 0692561 A1 19960117; **EP 0692561 B1 20000503**; DE 69516590 D1 20000608; DE 69516590 T2 20010222; FR 2722513 A1 19960119; FR 2722513 B1 19960830; JP 2928472 B2 19990803; JP H0860459 A 19960305; US 5575141 A 19961119

DOCDB simple family (application)

EP 95440038 A 19950704; DE 69516590 T 19950704; FR 9408883 A 19940713; JP 17757595 A 19950713; US 50181695 A 19950713