

Title (en)

Method for detecting unacceptable operating conditions in an electronically controlled laundry drier

Title (de)

Verfahren zur Erkennung von unzulässigen Betriebszuständen in elektronisch gesteuerten Wäschetrocknern

Title (fr)

Procédé pour détecter des conditions de fonctionnement inacceptables dans un sèche-linge commandé électroniquement

Publication

EP 0906985 B1 20021106 (DE)

Application

EP 98115844 A 19980821

Priority

DE 19741160 A 19970918

Abstract (en)

[origin: DE19741160A1] The conductivity is recorded periodically during the drying process and the actual measured value is compared to at least one previously registered value. When the change in the conductivity value corresponds to a preset narrow fluctuation range, a display indicates the drum (1) is at a standstill.

IPC 1-7

D06F 58/28

IPC 8 full level

D06F 58/50 (2020.01); **D06F 58/36** (2020.01)

CPC (source: EP US)

D06F 58/50 (2020.02 - EP US); **D06F 58/36** (2020.02 - EP US); **D06F 2103/00** (2020.02 - EP US); **D06F 2103/04** (2020.02 - EP US);
D06F 2103/10 (2020.02 - EP US); **D06F 2103/24** (2020.02 - EP US); **D06F 2103/34** (2020.02 - EP US); **D06F 2103/44** (2020.02 - EP US);
D06F 2105/46 (2020.02 - EP US); **D06F 2105/58** (2020.02 - EP US); **D06F 2105/62** (2020.02 - EP US)

Cited by

DE102006025952A1; WO2007141139A1

Designated contracting state (EPC)

CH DE FR GB IT LI NL

DOCDB simple family (publication)

DE 19741160 A1 19990325; DE 59806170 D1 20021212; EP 0906985 A1 19990407; EP 0906985 B1 20021106; US 6055744 A 20000502

DOCDB simple family (application)

DE 19741160 A 19970918; DE 59806170 T 19980821; EP 98115844 A 19980821; US 15643898 A 19980918