



(11) **EP 1 782 942 B8**

(12) **CORRECTED EUROPEAN PATENT SPECIFICATION**

(15) Correction information:
Corrected version no 1 (W1 B1)
Corrections, see
Bibliography INID code(s) 22

(51) Int Cl.:
B29C 73/10 (2006.01) **B29C 73/34** (2006.01)
B64F 5/00 (2006.01) **F24J 1/00** (2006.01)

(48) Corrigendum issued on:
21.03.2012 Bulletin 2012/12

(45) Date of publication and mention
of the grant of the patent:
04.01.2012 Bulletin 2012/01

(21) Application number: **06076966.8**

(22) Date of filing: **02.11.2006**

(54) **Fast line maintenance repair method for composite structures**

Verfahren zur Reparatur und schneller Wartung für Verbundstrukturen

Méthode de réparation et de maintenance rapide pour structures composites

(84) Designated Contracting States:
AT BE BG CH CY CZ DE DK EE ES FI FR GB GR
HU IE IS IT LI LT LU LV MC NL PL PT RO SE SI
SK TR

(30) Priority: **02.11.2005 US 163872**

(43) Date of publication of application:
09.05.2007 Bulletin 2007/19

(73) Proprietor: **The Boeing Company**
Chicago IL 66066-2016 (US)

(72) Inventors:
• **Keller, Russell L.**
Maple Valley, WA 98038 (US)

• **Spalding, John F.**
Renton WA 98055 (US)
• **Blanchard, Steven D.**
Issaquah, WA 98027 (US)

(74) Representative: **Land, Addick Adrianus Gosling et**
al
Arnold & Siedsma
Sweelinckplein 1
2517 GK Den Haag (NL)

(56) References cited:
US-A1- 4 560 428 US-A1- 5 442 156
US-A1- 5 865 397 US-B1- 6 652 690

Note: Within nine months of the publication of the mention of the grant of the European patent in the European Patent Bulletin, any person may give notice to the European Patent Office of opposition to that patent, in accordance with the Implementing Regulations. Notice of opposition shall not be deemed to have been filed until the opposition fee has been paid. (Art. 99(1) European Patent Convention).

EP 1 782 942 B8