

Title (en)
DECLUTCHING MECHANISM FOR A HAULING APPARATUS THROUGH WHICH RUNS A CABLE

Publication
EP 0070230 B1 19850410 (FR)

Application
EP 82401265 A 19820706

Priority
FR 8113553 A 19810709

Abstract (en)
[origin: US4438659A] A release mechanism is provided ensuring simultaneous opening of the two clamps of a traction apparatus for freeing the cable which passes therethrough. The release lever is mounted for longitudinal sliding by actuation of the handle while moving the intermediate pin carried by the warping out lever. A pivoting bolt, mounted in a widened end of a longitudinal oblong slit of said lever, prevents the release movement. The release can only be obtained when the user frees said bolt with one hand against the return action of a spring and, with the other hand, operates simultaneously said handle.

IPC 1-7
B66D 3/02

IPC 8 full level
B25B 25/00 (2006.01); **B66D 3/02** (2006.01)

CPC (source: EP US)
B66D 3/02 (2013.01 - EP US); **Y10T 74/20648** (2015.01 - EP US); **Y10T 74/20714** (2015.01 - EP US)

Cited by
US9693777B2; US9757124B2; US9820738B2; US9839422B2; US9839423B2; US9884456B2; US10004497B2; US10335145B2; US10426463B2; US10426467B2; US10426471B2; US10456137B2; US10517595B2; US10517596B2; US10603036B2; US11571210B2; US9642620B2; US9814462B2; US9987000B2; US10052044B2; US10206605B2; US10327767B2; US10363036B2; US10390841B2; US10542979B2; US10548504B2; US10675024B2; US10702270B2; US10980539B2; US11000278B2; US7303108B2; US9700309B2; US9782169B2; US9901346B2; US9901342B2; US9901344B2; US9901345B2; US9980729B2; US9993258B2; US9999426B2; US10004505B2; US10226250B2; US10245029B2; US10245030B2; US10307163B2; US10368864B2; US10413291B2; US10433837B2; US10470764B2; US10653413B2; US10675035B2; US7367485B2; US9750498B2; US9795381B2; US9962158B2; US9987003B2; US10092292B2; US10299787B2; US10327765B2; US10363033B2; US10368863B2; US10441280B2; US10765429B2; US11517325B2; US9603991B2; US9707005B2; US9844375B2; US9861359B2; US9913648B2; US10070861B2; US10076325B2; US10206678B2; US10258418B2; US10293100B2; US10314589B2; US10335151B2; US10342541B2; US10383633B2; US10405859B2; US10420561B2; US10420560B2; US10426481B2; US10485546B2; US10485536B2; US10568625B2; US10575868B2; US10660640B2; US10842524B2; US10893864B2; US6959852B2; US9924944B2; US10052104B2; US10064621B2; US10064688B2; US10172620B2; US10213262B2; US10265068B2; US10307160B2; US10327777B2; US10478188B2; US10524788B2; US10561420B2; US10736636B2; US11284890B2; US11690623B2; US9615826B2; US9629814B2; US9681870B2; US9770245B2; US10076326B2; US10085748B2; US10105139B2; US10117649B2; US10172619B2; US10238390B2; US10251648B2; US10265074B2; US10314587B2; US10357252B2; US10368865B2; US10390823B2; US10856866B2; US11039836B2; US11058418B2; US11272927B2; US9662110B2; US9743929B2; US9750499B2; US9757130B2; US9808246B2; US10028761B2; US10188385B2; US10201364B2; US10201363B2; US10245033B2; US10278722B2; US10299817B2; US10307159B2; US10357246B2; US10413293B2; US10441285B2; US10448948B2; US10463384B2; US10463383B2; US10499890B2; US10524790B2; US10531874B2; US10729436B2; US10729432B2; US10743849B2; US10893853B2; US9649111B2; US9687236B2; US9690362B2; US9733663B2; US9730695B2; US9795382B2; US9804618B2; US9826977B2; US9844373B2; US9943309B2; US9968355B2; US10004501B2; US10013049B2; US10070863B2; US10117653B2; US10136889B2; US10159482B2; US10245035B2; US10245027B2; US10285705B2; US10285699B2; US10314582B2; USD854151S; US10376263B2; US10413297B2; US10433846B2; US10485542B2; US10842489B2; US10842488B2; US10856868B2; US10869664B2; US10932774B2; US11224426B2; US11497488B2; US11622766B2; US9826978B2; US9848873B2; US10045781B2; US10045776B2; US10045778B2; US10064624B2; US10105136B2; US10130361B2; US10149682B2; US10166025B2; US10182819B2; US10238389B2; US10245032B2; US10258333B2; US10265072B2; US10335150B2; US10363037B2; US10368867B2; US10383630B2; US10398436B2; US10426469B2; US10433840B2; US10448950B2; US10478181B2; US10485541B2; US10687812B2; US10736628B2; US10765425B2; US10874391B2; US10898184B2; US11617575B2; US6905057B2; US9700310B2; US9795384B2; US9801634B2; US9808249B2; US9833236B2; US9839429B2; US9913647B2; US9918704B2; US9924947B2; US9924942B2; US9974529B2; US9974538B2; US9980713B2; US9987006B2; US10028743B2; US10045769B2; US10058327B2; US10130352B2; US10136890B2; US10194910B2; US10201349B2; US10206676B2; US10238385B2; US10238387B2; US10265067B2; US10335148B2; US10441281B2; US10463372B2; US10470763B2; US10517590B2; US10588612B2; US10624634B2; US10796471B2; US10828032B2; US11006951B2; US11918209B2; US9603595B2; US9649110B2; US9675372B2; US9706991B2; US9801626B2; US9814460B2; US9826976B2; US9839428B2; US9839420B2; US9844368B2; US9867618B2; US9867612B2; US9872684B2; US9872682B2; US9877723B2; US10085751B2; US10117652B2; US10136887B2; US10149680B2; US10172616B2; USD850617S; US10405857B2; US10413294B2; US10420550B2; US10420555B2; US10420549B2; US10448952B2; US10456133B2; US10470770B2; US10485537B2; US10595862B2; US10687806B2; US10881396B2; US11058423B2; US7000819B2; US9603598B2; US9629623B2; US9629629B2; US9675355B2; US9687237B2; US9724091B2; US9730692B2; US9750501B2; US9808244B2; US9833242B2; US9839427B2; US9844374B2; US9844376B2; US9883860B2; US9888919B2; US9895147B2; US9968356B2; US9999431B2; US10028742B2; US10130363B2; US10149683B2; US10149679B2; US10180463B2; US10213201B2; US10226249B2; US10238391B2; US10285695B2; US10307170B2; US10390825B2; US10433844B2; US10470762B2; US10517594B2; US10912575B2; US10973516B2; US11160551B2; US11179150B2; US11213293B2; US7128254B2; US9724092B2; US9775614B2; US9788834B2; US9795383B2; US9801628B2; US9801627B2; US9808247B2; US9833238B2; US9844372B2; US9848875B2; US9861361B2; US9883861B2; US9962161B2; US10004506B2; US10123798B2; US10130366B2; US10206677B2; US10211586B2; US10213198B2; US10231794B2; US10238386B2; US10258330B2; US10258332B2; US10327764B2; US10327766B2; US10357247B2; US10363031B2; US10398433B2; US10405854B2; US10426476B2; US10426478B2; US10426477B2; US10492785B2; US10568652B2; US10588623B2; US10617412B2; US10918385B2; US11141153B2; US11191539B2; US7364061B2; US9724094B2; US9737301B2; US9757128B2; US9788836B2; US9833241B2; US9844369B2; US9877721B2; US9931118B2; US9993248B2; US10010322B2; US10010324B2; US10016199B2; US10045779B2; US10058963B2; US10071452B2; US10098636B2; US10111679B2; US10130359B2; US10135242B2; US10159483B2; US10182816B2; US10245028B2; US10258336B2; US10299792B2; US10321907B2; US10327769B2; US10335144B2; US10342533B2; US10470768B2; US10485539B2; US10542988B2; US10653417B2; US10695053B2; US10758233B2; US10835249B2; US10842491B2; US10993717B2; US11051811B2; US11058420B2; US11058425B2; US11129615B2; US11185330B2; US11406379B2; US11517315B2; US7059508B2; US9724098B2; US9763662B2; US9844379B2; US9895148B2; US9913642B2; US9918716B2; US9924961B2; US9968354B2; US10039529B2; US10188393B2; US10258331B2; US10265065B2; US10271851B2; US10271846B2; US10278697B2; US10278702B2; USD847989S; US10292707B2; US10299878B2; US10314590B2; USD851762S; US10321909B2; US10342543B2; US10383634B2; US10398434B2; US10420552B2; US10420553B2; US10433849B2; US10456140B2; US10463369B2; US10485547B2;

US10492787B2; US10595835B2; US10675021B2; US10682136B2; US10709446B2; US10716614B2; US10765424B2; US10945727B2; US11045191B2; US7434715B2; US9907620B2; US10004498B2; US10028744B2; US10052099B2; US10052100B2; US10052102B2; US10098642B2; US10166026B2; US10188394B2; US10213203B2; US10278780B2; US10292704B2; US10357251B2; US10390829B2; US10433845B2; US10433918B2; US10441369B2; US10463370B2; US10470769B2; US10517682B2; US10517599B2; US10639115B2; US10751138B2; US10779822B2; US10828028B2; US10980538B2; US11000277B2; US11058426B2; US11064998B2; US11103248B2

Designated contracting state (EPC)

AT BE CH DE GB IT LI LU NL SE

DOCDB simple family (publication)

EP 0070230 A1 19830119; EP 0070230 B1 19850410; AT E12619 T1 19850415; BR 8203978 A 19830705; CS 257256 B2 19880415; DE 3262978 D1 19850515; DE 70230 T1 19830526; FR 2509490 A1 19830114; FR 2509490 B1 19850222; JP H0343029 B2 19910701; JP S5828472 A 19830219; US 4438659 A 19840327; YU 147182 A 19880430; YU 45542 B 19920528; ZA 824799 B 19830427

DOCDB simple family (application)

EP 82401265 A 19820706; AT 82401265 T 19820706; BR 8203978 A 19820708; CS 523282 A 19820708; DE 3262978 T 19820706; DE 82401265 T 19820706; FR 8113553 A 19810709; JP 11787082 A 19820708; US 39654082 A 19820708; YU 147182 A 19820706; ZA 824799 A 19820706