

Title (en)
PROCESS AND APPARATUS TO DRAW OFF WASTE SELVEDGE IN LOOMS

Publication
EP 0253036 B1 19890315 (FR)

Application
EP 86401607 A 19860718

Priority
EP 86401607 A 19860718

Abstract (en)
[origin: EP0253036A1] 1. Method for removing waste slivers produced by cutting false selvages, of the type comprising a step of coiling said slivers in the form of spiral turns and a discharge step, characterized in that a single cord formed by the slivers is subjected to a false twist, producing a winding of the slivers one in respect of the other, which permits to automatically balance their tensions, the cord so formed being then coiled in the form of successive spiral turns.

IPC 1-7
D03D 47/40; **D03J 1/00**

IPC 8 full level
D03D 47/40 (2006.01); **D03J 1/00** (2006.01)

CPC (source: EP)
D03D 47/40 (2013.01); **D03J 1/002** (2013.01)

Designated contracting state (EPC)
BE CH DE IT LI

DOCDB simple family (publication)
EP 0253036 A1 19880120; **EP 0253036 B1 19890315**; DE 3662406 D1 19890420; FR 2576610 A1 19860801; FR 2576610 B1 19880318

DOCDB simple family (application)
EP 86401607 A 19860718; DE 3662406 T 19860718; FR 8501259 A 19850128