

Title (en)

MISPICK REMOVING DEVICE FOR AN AIR JET LOOM

Publication

EP 0310804 A3 19910918 (DE)

Application

EP 88113844 A 19880825

Priority

DE 3730480 A 19870911

Abstract (en)

[origin: EP0310804A2] In a method for removing an incorrectly introduced weft yarn on an air-jet loom, the incorrectly introduced weft yarn is not severed from the weft yarn supplied, after which predetermined length portions calculated to be smaller than double the weft-yarn length are released from the supplied weft yarn and are shot in a pulse-like manner through the shed which in the meantime has been restored and which exposes the incorrectly introduced weft yarn. <IMAGE>

IPC 1-7

D03D 47/30

IPC 8 full level

D03D 47/30 (2006.01); **D03D 51/08** (2006.01)

CPC (source: EP US)

D03D 47/3013 (2013.01 - EP US); **D03D 47/308** (2013.01 - EP US); **D03D 47/3086** (2013.01 - EP US); **D03D 51/085** (2013.01 - EP US)

Citation (search report)

- [AD] EP 0207470 A2 19870107 - NISSAN MOTOR [JP]
- [A] US 4133353 A 19790109 - LARMIT ADRIANUS J F

Cited by

EP2098625A1; WO2023280510A1; EP0393468A1; CH682244A5; EP0561218A1; US5322090A; DE4209686A1; JPH062247A; BE1018036A3; BE1008058A3; DE19521100C1; EP0747520A3; US5746256A; DE29721042U1; US6050304A; DE19521106A1; US5642759A; EP0747519A3; EP0747520A2; WO2011000561A1; DE102021207297B3

Designated contracting state (EPC)

BE CH DE ES FR GB IT LI LU NL SE

DOCDB simple family (publication)

EP 0310804 A2 19890412; **EP 0310804 A3 19910918**; **EP 0310804 B1 19931124**; DE 3730480 A1 19890330; DE 3885847 D1 19940105; US 4898214 A 19900206

DOCDB simple family (application)

EP 88113844 A 19880825; DE 3730480 A 19870911; DE 3885847 T 19880825; US 24212388 A 19880909