

Title (en)

SAFETY DEVICE FOR LAUNDRY DRIER

Publication

EP 0312072 B1 19930317 (EN)

Application

EP 88117066 A 19881013

Priority

IT 4574687 A 19871014

Abstract (en)

[origin: EP0312072A1] A safety device for a laundry drier adapted to cut the electric power supply to the machine in case of insufficient or totally absent drying air circulation due to clogging of the filter (14) and/or stoppage of the electric motor (23) of the blower (9) and the drum (5) caused by failure or functional defects of the motor. The safety device comprises control means (18,37,19; 44,37,19; 48) connected to the heater element (13) and to the protection thermostat (15) of the machine for controlling the power supply to the machine or the interruption thereof as a function of the reset time of the protection thermostat (15) after the response temperature of the thermostat has been attained.

IPC 1-7

D06F 58/28

IPC 8 full level

D06F 58/28 (2006.01)

CPC (source: EP US)

D06F 37/42 (2013.01 - EP US); **D06F 34/08** (2020.02 - EP US); **D06F 58/50** (2020.02 - EP US); **D06F 2103/32** (2020.02 - EP US);
D06F 2103/38 (2020.02 - EP US); **D06F 2103/44** (2020.02 - EP US); **D06F 2105/28** (2020.02 - EP US); **D06F 2105/62** (2020.02 - EP US)

Cited by

US8955232B2; DE102007042060B4; US2010000118A1; DE102007062070B4; EP0889155A1; CN101818446A; US2011030238A1;
EP0512940A1; EP0371263A1; DE4337735A1; DE4337735C2; DE19704213C1; DE102007062069B4; DE4034274A1; EP0483731A3;
CN103361950A; US7992320B2; US6671977B2; US9897377B2; WO2007004198A1; WO0204736A3; US9435587B2

Designated contracting state (EPC)

DE FR GB IT SE

DOCDB simple family (publication)

EP 0312072 A1 19890419; EP 0312072 B1 19930317; DE 3879357 D1 19930422; DE 3879357 T2 19930624; IT 1220063 B 19900606;
IT 8745746 A0 19871014

DOCDB simple family (application)

EP 88117066 A 19881013; DE 3879357 T 19881013; IT 4574687 A 19871014