

Title (en)
APPARATUS FOR MERCERIZING A FABRIC

Publication
EP 0328487 B1 19920429 (DE)

Application
EP 89810085 A 19890201

Priority
CH 49588 A 19880211

Abstract (en)
[origin: EP0328487A1] The operator's stand (13) is in front of the stenter inlet and above the treatment zone (5), the floor of the stand being at a lower level than the stenter inlet. The treatment zone forms an arcuate bypass consisting of alternate fixed rolls (21) and adjustable rolls (22). The stand facilitates access to the stenter inlet, yet the roll arrangement ensures a tight strand of guiding. <IMAGE>

IPC 1-7
D06B 3/34; **D06B 7/08**; **D06B 23/04**

IPC 8 full level
D06B 3/34 (2006.01); **D06B 7/08** (2006.01); **D06B 23/04** (2006.01)

CPC (source: EP)
D06B 3/345 (2013.01); **D06B 7/08** (2013.01); **D06B 23/04** (2013.01)

Cited by
DE102015224029A1

Designated contracting state (EPC)
BE CH DE ES FR IT LI NL

DOCDB simple family (publication)
EP 0328487 A1 19890816; **EP 0328487 B1 19920429**; **EP 0328487 B2 19960327**; CH 678199 A5 19910815; DE 58901251 D1 19920604

DOCDB simple family (application)
EP 89810085 A 19890201; CH 49588 A 19880211; DE 58901251 T 19890201