

Publication

EP 0886017 A3 19990127

Application

EP 98111097 A 19980617

Priority

DE 19726480 A 19970621

Abstract (en)

[origin: EP0886017A2] The crosspiece (11) of a roof ridge section retainer has weak points defining two bending lines (18,19). The bending lines are spaced apart and run transverse to the longitudinal direction of the crosspiece. The bending lines are positioned between first (12) and second fastening strips which are fastened opposite sides of the crosspiece and run transverse to the planes of the strips. Preferably, the fastening strips have a number of weak points, formed by rows of holes (24,25) which define bending folding lines.

IPC 1-7

E04D 12/00; E04D 13/17

IPC 8 full level

E04D 12/00 (2006.01)

CPC (source: EP)

E04D 12/008 (2013.01)

Citation (search report)

- [A] US 5380116 A 19950110 - COLONIAS KAREN W [US]
- [DA] DE 3317334 C1 19840726 - GEHRING MANFRED
- [A] DE 9317696 U1 19940203 - REDLAND DAKPROD BV [NL]
- [A] FR 2434246 A1 19800321 - REDLAND BRAAS NV [NL]
- [A] DE 8626872 U1 19861120
- [A] DE 3713442 A1 19881103 - BILSTEIN AUGUST GMBH CO KG [DE]
- [A] DE 9310019 U1 19931028 - SOCHA RUDOLF [DE]

Designated contracting state (EPC)

AT BE CH CY DE DK ES FI FR GB GR IE IT LI LU MC NL PT SE

DOCDB simple family (publication)

EP 0886017 A2 19981223; EP 0886017 A3 19990127; DE 19726480 A1 19990121

DOCDB simple family (application)

EP 98111097 A 19980617; DE 19726480 A 19970621