

Title (en)

SYSTEM AND METHOD FOR JOINT RESURFACE REPAIR

Title (de)

SYSTEM UND VERFAHREN FÜR DIE REPARATUR VON GELENKOVERFLÄCHEN

Title (fr)

SYSTEME ET PROCEDE DE RECONSTITUTION DES SURFACES ARTICULAIRES

Publication

EP 1455665 A4 20090610 (EN)

Application

EP 02805182 A 20021217

Priority

- US 0240310 W 20021217
- US 2407701 A 20011217
- US 16253302 A 20020604
- US 0148821 W 20011217
- US 20104900 P 20000501

Abstract (en)

[origin: WO03051210A2] An implant for installation into a portion of an articular surface includes a protrusion configured to cover and un-excised portion of articular surface proximate to the implant. Another implant may form a cavity to allow the un-excised portion of articular surface to remodel over a perimeter edge of the implant. The implant may also include indentations such as grooves to promote articular cartilage remodeling over a portion of the load bearing surface of the implant. An elongated or non-round implant is also provided having two opposing concentric arcuate shaped sides, as well as a method to seat such an implant in an articular surface. A method for seating an implant without cutting articular cartilage is also provided.

IPC 1-7

A61B 17/58; A61F 2/38

IPC 8 full level

A61B 17/56 (2006.01); **A61B 17/04** (2006.01); **A61B 17/16** (2006.01); **A61B 17/17** (2006.01); **A61B 17/58** (2006.01); **A61B 17/68** (2006.01);
A61B 17/88 (2006.01); **A61B 19/00** (2006.01); **A61F 2/30** (2006.01); **A61F 2/46** (2006.01); **A61F 2/64** (2006.01); **A61F 2/76** (2006.01);
A61B 17/00 (2006.01); **A61B 17/06** (2006.01); **A61B 17/32** (2006.01); **A61B 17/86** (2006.01); **A61F 2/00** (2006.01); **A61F 2/38** (2006.01)

CPC (source: EP)

A61B 17/0401 (2013.01); **A61B 17/1615** (2013.01); **A61B 17/1675** (2013.01); **A61B 17/1764** (2013.01); **A61B 17/8615** (2013.01);
A61B 17/888 (2013.01); **A61B 90/06** (2016.02); **A61F 2/30756** (2013.01); **A61F 2/30942** (2013.01); **A61F 2/4618** (2013.01);
A61F 2/4657 (2013.01); **A61B 5/4528** (2013.01); **A61B 17/0487** (2013.01); **A61B 17/06166** (2013.01); **A61B 17/1635** (2013.01);
A61B 17/1637 (2013.01); **A61B 17/32053** (2013.01); **A61B 17/8625** (2013.01); **A61B 17/863** (2013.01); **A61B 17/8695** (2013.01);
A61B 17/8805 (2013.01); **A61B 17/8827** (2013.01); **A61B 17/8875** (2013.01); **A61B 17/8894** (2013.01); **A61B 2017/00238** (2013.01);
A61B 2017/00464 (2013.01); **A61B 2017/0404** (2013.01); **A61B 2017/0409** (2013.01); **A61B 2017/044** (2013.01); **A61B 2017/0445** (2013.01);
A61B 2017/0448 (2013.01); **A61B 2017/045** (2013.01); **A61B 2090/061** (2016.02); **A61F 2/30767** (2013.01); **A61F 2/3859** (2013.01);
A61F 2/4603 (2013.01); **A61F 2002/30065** (2013.01); **A61F 2002/30069** (2013.01); **A61F 2002/30113** (2013.01); **A61F 2002/30143** (2013.01);
A61F 2002/30225 (2013.01); **A61F 2002/30299** (2013.01); **A61F 2002/30324** (2013.01); **A61F 2002/30332** (2013.01); **A61F 2002/30354** (2013.01);
A61F 2002/30433 (2013.01); **A61F 2002/30448** (2013.01); **A61F 2002/30451** (2013.01); **A61F 2002/30604** (2013.01); **A61F 2002/30719** (2013.01);
A61F 2002/30772 (2013.01); **A61F 2002/30831** (2013.01); **A61F 2002/30858** (2013.01); **A61F 2002/30871** (2013.01); **A61F 2002/30873** (2013.01);
A61F 2002/30878 (2013.01); **A61F 2002/30879** (2013.01); **A61F 2002/30892** (2013.01); **A61F 2002/30896** (2013.01); **A61F 2002/30943** (2013.01);
A61F 2002/30948 (2013.01); **A61F 2002/30952** (2013.01); **A61F 2002/30957** (2013.01); **A61F 2002/4635** (2013.01); **A61F 2002/4658** (2013.01);
A61F 2002/4661 (2013.01); **A61F 2002/4662** (2013.01); **A61F 2002/4663** (2013.01); **A61F 2002/4681** (2013.01); **A61F 2210/0071** (2013.01);
A61F 2220/0033 (2013.01); **A61F 2220/0041** (2013.01); **A61F 2220/005** (2013.01); **A61F 2220/0058** (2013.01); **A61F 2230/0006** (2013.01);
A61F 2230/0017 (2013.01); **A61F 2230/0069** (2013.01); **A61F 2230/0093** (2013.01); **A61F 2250/0036** (2013.01); **A61F 2250/0092** (2013.01);
A61F 2310/00017 (2013.01); **A61F 2310/00023** (2013.01); **A61F 2310/00029** (2013.01); **A61F 2310/00059** (2013.01); **A61F 2310/00089** (2013.01);
A61F 2310/00095 (2013.01); **A61F 2310/00203** (2013.01); **A61F 2310/00239** (2013.01); **A61F 2310/00796** (2013.01)

Citation (search report)

- [X] US 4896663 A 19900130 - VANDEWALLS MARK V [US]
- [X] US 5885298 A 19990323 - HERRINGTON STEPHEN MICHAEL [US], et al
- [X] US 4998938 A 19910312 - GHAJAR JAMSHID B G [US], et al
- [X] US 6206885 B1 20010327 - GHAREMANI FATHALI [US], et al
- [XA] WO 0182677 A2 20011108 - STD MFG INC [US], et al
- See references of WO 03051210A2

Designated contracting state (EPC)

AT BE BG CH CY CZ DE DK EE ES FI FR GB GR IE IT LI LU MC NL PT SE SI SK TR

DOCDB simple family (publication)

WO 03051210 A2 20030626; WO 03051210 A3 20040325; AT E427701 T1 20090415; AU 2001259327 B2 20050217;
AU 2002248198 A1 20030630; AU 2002357284 A1 20030630; AU 2002357284 B2 20070816; AU 5932701 A 20011112;
CA 2407440 A1 20011108; CA 2470194 A1 20030626; CA 2470194 C 20110201; CA 2470936 A1 20030626; CA 2470936 C 20120207;
DE 60138275 D1 20090520; DK 1278460 T3 20090810; EP 1278460 A2 20030129; EP 1278460 A4 20041013; EP 1278460 B1 20090408;
EP 1455665 A2 20040915; EP 1455665 A4 20090610; EP 1455666 A1 20040915; EP 1455666 A4 20090610; EP 2062541 A2 20090527;
EP 2062541 A3 20090812; EP 2062541 B1 20180711; EP 2481368 A1 20120801; EP 2481368 B1 20141217; ES 2324282 T3 20090804;
JP 2003531657 A 20031028; JP 2005511238 A 20050428; JP 2005512632 A 20050512; WO 0182677 A2 20011108; WO 0182677 A3 20020411;
WO 03051211 A1 20030626

DOCDB simple family (application)

US 0240310 W 20021217; AT 01932833 T 20010501; AU 2001259327 A 20010501; AU 2002248198 A 20011217; AU 2002357284 A 20021217;
AU 5932701 A 20010501; CA 2407440 A 20010501; CA 2470194 A 20021217; CA 2470936 A 20011217; DE 60138275 T 20010501;
DK 01932833 T 20010501; EP 01932833 A 20010501; EP 01997077 A 20011217; EP 02805182 A 20021217; EP 09002088 A 20010501;

EP 12002103 A 20011217; ES 01932833 T 20010501; JP 2001579575 A 20010501; JP 2003552147 A 20021217; JP 2003552148 A 20011217;
US 0114061 W 20010501; US 0148821 W 20011217