

Title (en)

METHOD FOR DISPLAYING DEVICE PARAMETER VALUES OF INDUSTRIAL SWITCH DEVICES

Title (de)

VERFAHREN ZUR ANZEIGE VON GERAETEPARAMETERWERTEN AN INDUSTRIESCHALTGERAETEN

Title (fr)

PROCÉDÉ D’AFFICHAGE DE VALEURS DE PARAMÈTRES D’APPAREILS SUR DES APPAREILS DE COMMUTATION

Publication

EP 2652765 A1 20131023 (DE)

Application

EP 11797312 A 20111213

Priority

- EP 10194702 A 20101213
- EP 2011072544 W 20111213
- EP 11797312 A 20111213

Abstract (en)

[origin: EP2463886A1] The method involves adjusting switching device parameters by an adjusting device (20) at an industrial switching device in remote manner. Parameter values are displayed by a separate display (15). The parameter values displayed in the display are read from the adjusting device of the industrial switching device. The adjusted parameter values with constant frequency are output to the display during change of the parameter values by the adjusting device of the industrial switching device. The adjusting device is provided with a device for reading adjusting values. An independent claim is also included for a device for executing a method for securing compliance of actual adjustable parameter values of an industrial switching device.

IPC 8 full level

H01H 71/74 (2006.01); **H01C 10/14** (2006.01); **H01H 71/12** (2006.01)

CPC (source: EP)

H01C 10/14 (2013.01)

Citation (search report)

See references of WO 2012080211A1

Designated contracting state (EPC)

AL AT BE BG CH CY CZ DE DK EE ES FI FR GB GR HR HU IE IS IT LI LT LU LV MC MK MT NL NO PL PT RO RS SE SI SK SM TR

DOCDB simple family (publication)

EP 2463886 A1 20120613; CN 103348436 A 20131009; CN 103348436 B 20160601; EP 2652765 A1 20131023; EP 2652765 B1 20170322; WO 2012080211 A1 20120621

DOCDB simple family (application)

EP 10194702 A 20101213; CN 201180067288 A 20111213; EP 11797312 A 20111213; EP 2011072544 W 20111213