



(11) **EP 2 371 523 B8**

(12) **CORRECTED EUROPEAN PATENT SPECIFICATION**

(15) Correction information:
Corrected version no 1 (W1 B1)
Corrections, see
Bibliography INID code(s) 73

(51) Int Cl.:
B29C 73/12 ^(2006.01) **B29C 73/10** ^(2006.01)
B29C 73/32 ^(2006.01) **B29L 31/30** ^(2006.01)

(48) Corrigendum issued on:
02.09.2015 Bulletin 2015/36

(45) Date of publication and mention
of the grant of the patent:
15.07.2015 Bulletin 2015/29

(21) Application number: **11160028.4**

(22) Date of filing: **28.03.2011**

(54) **A method for repairing parts of composite material of an aircraft**

Verfahren zum Reparieren von Teilen aus Verbundmaterial eines Flugzeugs

Procédé pour réparer des pièces en matériau composite d'un avion

(84) Designated Contracting States:
AL AT BE BG CH CY CZ DE DK EE ES FI FR GB
GR HR HU IE IS IT LI LT LU LV MC MK MT NL NO
PL PT RO RS SE SI SK SM TR

(30) Priority: **29.03.2010 IT TO20100238**

(43) Date of publication of application:
05.10.2011 Bulletin 2011/40

(73) Proprietor: **Alenia Aermacchi S.p.A.**
00195 Roma (IT)

(72) Inventors:
• **Cacace, Pierluigi**
I-74020, MONTEIASI (Taranto) (IT)
• **Gallo, Nicola**
I-74121, TARANTO (IT)

(74) Representative: **Fioravanti, Corrado et al**
Jacobacci & Partners S.p.A.
Corso Emilia 8
10152 Torino (IT)

(56) References cited:
US-A1- 2009 294 053 US-B1- 6 435 242

Note: Within nine months of the publication of the mention of the grant of the European patent in the European Patent Bulletin, any person may give notice to the European Patent Office of opposition to that patent, in accordance with the Implementing Regulations. Notice of opposition shall not be deemed to have been filed until the opposition fee has been paid. (Art. 99(1) European Patent Convention).

EP 2 371 523 B8