

Title (en)

A vehicle inspection pit cover

Title (de)

Fahrzeuginspektionsgrubendeckel

Title (fr)

Couvercle de fosse d'inspection de véhicule

Publication

EP 2886747 B1 20170927 (EN)

Application

EP 14179383 A 20140731

Priority

GB 201313834 A 20130802

Abstract (en)

[origin: GB2517682A] A cover for a vehicle inspection and repair pit (1) comprises at least one cover plate (14) for covering the pit (1) and a hydraulic piston (22) to open and close the pit. The cover is hingedly mounted to the opening of the pit so the cover can be rotated into a stowed position. Once in a covered position another piston 28 can lock the cover in place, and retract to allow the cover to be rotated or swivelled back into a stored position.

IPC 8 full level

E04H 5/06 (2006.01)

CPC (source: EP GB)

E04H 5/06 (2013.01 - EP); **E04H 6/428** (2013.01 - GB)

Cited by

CN113914683A; CN113513673A; CN113027187A; CN109914875A; CN109138545A

Designated contracting state (EPC)

AL AT BE BG CH CY CZ DE DK EE ES FI FR GB GR HR HU IE IS IT LI LT LU LV MC MK MT NL NO PL PT RO RS SE SI SK SM TR

DOCDB simple family (publication)

GB 201313834 D0 20130918; GB 2517682 A 20150304; EP 2886747 A1 20150624; EP 2886747 B1 20170927; ES 2654685 T3 20180214

DOCDB simple family (application)

GB 201313834 A 20130802; EP 14179383 A 20140731; ES 14179383 T 20140731